## ABSTRACT OF THE DISCLOSURE

If an edge of a sheet metal of a image forming apparatus damages an electric cable, the image signal is distorted and no correct image is formed since the damage causes feeding failure and signal deterioration. This is remarkable in the conventional digital electrophotographic apparatus, since the drive signal to drive a laser or a light emitting diode(LED) for exposing the photosensitive body becomes higher in frequency as a resolution and speed are increased and tends to generate the electric noise. In order to prevent damage of an electric cable by a metal frame, an apparatus having a holder for holding a feed cable is provided.

15

10

5